

(217) 782 - 5544

April 3, 1986

Ms. Ann Budich U.S. Environmental Protection Agency 230 South Dearborn Street 5 HW-13 Chicago, Illinois 60604

Re: Report of Non-Notifier and Non-Filer Apollo Metal ILD 005070131

Dear Ms. Budich:

Enclosed is information relating to the Apollo Metal facility, a Non-Notifier and Non-Filer under RCRA. If after followup by this Agency, this Company does not come into compliance, we will refer this matter for enforcement.

Sincerely yours,

Paul R. Jagfello

Attorney

Enforcement Programs

PRJ:mm

Enclosure

cc: Gary King Glen Savage

Bur Filson (w/enclosure)

Northern Region



217/782-6761

Refer to: C31ECC5161 -- Cook County

Apollo Hetal ILEGOSO70131

COMPLIANCE IMPURY LETTER-

Certifled & D 57/ 158675

April 1, 1988

Apollo Metal Attm: Mr. Shemasco 11500 W. King Street Franklin Park, IL 60131

Dear Mr. Sharasco:

The purpose of this letter is to address the status of the above-referenced facility in relation to the requirements of 35 III. Adm. Code Part 722.

Subparts B. C. D and E and 35 III. Adm. Code Part 725, Subparts B. C. D. E and I and to inquire as to your position with respect to the apparent violations identified in Attachment A and your plans to correct these apparent violations. The Agency's findings of apparent non-compliance in Attachment A are based on an inspection completed on Narch 7, 1986. For your convenience a copy of the inspection report is enclosed with this letter.

Please submit in writing, within fifteen (15) calendar days of the date of this letter, the reasons for the identified violations, a description of the steps which have been taken to correct the violations and a schedule, including dates, by which each violation will be resolved. The written response should be sent to the following:

Mark A. Haney, Manager
Facilities Compliance Unit
Compliance Menitoring Section
Illinois Environmental Protection Agency
Division of Land Pollution Control
2200 Churchill Road
Springfield, Illinois 62706

In addition, include in your response two copies of your waste analysis plan, waste analyses, inspection schedule, inspection log, description of the type and amount of personnel training, job titles, job descriptions, training records to document training, proof of arrangements attempted with local emergency response organizations, contingency plan, facility and generator annual reports for 1983, 1984 and 1985, closure plan, cost estimate for facility closure, canifests for wastes shipped off-site in 1983, 1984 and 1985, subsequent notification for hazardous waste storage (USEPA Form 8700-12) and a Part A permit application (USEPA Form 3510-1 and 3510-3).



Further, take notice that non-compliance with the requirements of the Illinois Environmental Protection Act and rules and regulations adopted thereunder may be the subject of enforcement action pursuent to either the Illinois Environmental Protection Act, Ill. Bev. Stat., Ch. Ill 1/2, Sec. 1001 et sec. or the federal Resource Conservation and Recovery Act (RCRA), 42 U.S.C. Sec. 6901 et seq.

If you have any questions regarding the above, please contact Gino Bruni at 312/245-9780.

Sincerely.

Mark A. Heney, Manager Facilities Compliance Unit Compilance Monitoring Section Division of Land Pollution Control

FAH: EF: 68: 12907827/12-13

cc: Division File Northern Region Den Gimbel Gary King/ Bichelle Tebraque



#### Attachment A

Pursuant to 35 III. Adm. Code 703.121(a), no person shall conduct any bazardous waste storage, bazardous waste treatment or bezardous waste disposal operation:

- Without a RCRA point for the MM (bazardous waste ranagement) facility; or
- 2. In violation of any condition imposed by a RCRA permit.

You are in apparent violation of 35 Ill. Adm. Code 703.121(a) for the following reason(s): You are conducting hezardous waste storage without a RCRA permit.

Pursuant to 35 III. Adm. Code 703.150(a), the camer or operator of an existing HWM facility must submit Part A of the permit application to the Agency no later than the following times, whichever comes first:

- a. Six months after the date of publication of regulations which first require the owner or operator to comply with standards in 35 Ill.

  Adm. Code 725.
- b. Thirty days after the date the owner or operator first becomes subject to the standards in 35 Ill. Adm. Code 725.

You are in apparent violation of 35 Ill. Adm. Code 703.150(a) for the following reason(s): You have not submitted Part A of the permit application.

35 Ill. Adm. Code 722.140(a) requires the generator to keep a copy of each manifest signed in accordance with Section 722.123(a) for three years or until he receives a signed copy from the designated facility which received the waste. This signed copy must be retained as a record for at least three years from the date the waste was accepted by the initial transporter. You are in apparent violation of this Section in that no manifests were available during the inspection.

35 III. Adm. Code 722.140(b) requires the generator to keep a copy of each Annual Report and any Exception Report(s) for a period of at least three years from the due date. You are in apperent violation of this Section in that no annual reports were available during the inspection.

35 Ill. Adm. Code 722.140(c) requires the generator to keep records of any test results, waste analyses or other determinations made in accordance with Section 722.111 for at least three years from the date that the waste was last sent to on-site or off-site treatment, storage or disposal facility. You are in apparent violation of this Section in that no records of test results were available during the inspection.



Pursuant to 35 III. Adm. Code 725.113(a), the owner or operator is required to conduct a detailed chemical and physical analysis of a representative sample of hazardous waste prior to storage. You are in apparent violation of 35 III. Adm. Code 725.113(a) for the following reason(s): Ho analyses were conducted prior to storage.

Pursuant to 35 Ill. Adm. Code 725.113(b), the owner or operator must have on file at the facility a detailed written waste analysis plan describing the procedures to be used to compile data required under Section 725.113(a). You are in apparent violation of 35 Ill. Adm. Code 725.113(b) since no such plan was present at the site on the date of the inspection.

Pursuant to 35 Ill. Adm. Code 725.115(a), the owner or operator must inspect his facility for malfunctions and deterioration, operator errors and discharges that may be causing or may lead to a release to the environment or a threat to human health. You are in apparent violation of 35 Ill. Adm. Code 725.115(a) in that the required inspections are not being made:

Pursuant to 35 III. Adm. Code 725.115(b), the owner or operator must develop and follow a written schedule for inspection of all equipment and devices that are important to preventing, detecting or responding to environmental or human health hazards. This schedule must be kept at the facility and must identify the types of problems which are to be looked for during the inspection. The schedule should allow for daily inspection of areas subject to spills, when those areas are in use. You are in apparent violation of 35 III. Adm. Code 725.115(b) for the following reasons(s): No inspection schedule was available during the inspection.

Pursuant to 35 III. Adm. Code 725.115(d), the owner or operator must record inspections, and the specific data required by this Section in an inspection log or summary. These records must be kept for at least three years. You are in apparent violation of 35 III. Adm. Code 725.115(d) for the following reason(s): So inspection leg or summary was available during the inspection.

Pursuant to 35 Ill. Adm. Code 725.116(d), the owner or operator must maintain the following documents and records at the facility:

- a. The job title for each position at the facility related to hazardous waste management and the name of the employee filling each job;
- b. A written job description for each position listed under paragraph (d)(!) of this Section. This description may be consistent in its degree of specificity with descriptions for other similar positions in the same company location or bargaining unit, but must include the requisite skill, education or other qualifications and duties of facility personnel assigned to each position;
- c. A written description of the type and amount of both introductory and continuing training that will be given to each person filling a position listed under paragraph (d)(l) of this Section:



d. Records that document that the training or job experience required under paragraphs (a), (b) and (c) of this Section has been given to and completed by facility personnel.

You are in apparent violation of 35 Ill. Adm. Code 725. [16(d) in that item(s) a, b, c and d above were not maintained at the facility.

Pursuant to 35 III. Adm. Code 725.116(a), facility personnel must complete a program of classroom instruction or on-the-jeb training directed by a person trained in hazardous waste management procedures. The training must be designed to ensure that facility personnel are able to respond to emergencies. You are in apparent violation of 35 III. Adm. Code 725.116(a) for the following reason(s): No evidence that facility personnel had completed the required training was available during the inspection.

Pursuant to 35 III. Adm. Code 725.116(c), facility personnel must take part in an annual review of the initial training required in paragraph (a) of this Section. You are in apparent violation of this Section in that facility personnel have not received an annual review of the initial training.

Pursuant to 25 III. Adm. Code 725.117(a), the owner or operator must take precautions to prevent accidental ignition or reaction of ignitable or reactive waste. This waste must be separated and protected from sources of ignition or reaction. While ignitable or reactive waste is being handled, the owner or operator must confine smoking and open flame to specially designated locations. "No Smoking" signs must be conspicuously placed wherever there is a bezard from ignitable or reactive waste. You are in apparent violation of 25 III. Adm. Code 725.117(a) for the following reason(s): No "No Smoking" signs were observed during the inspection. No evidence that precautions are being taken to prevent accidental ignition or reaction of ignitable or reactive wastes were observed during the inspection.

Persuant to 35 III. Adm. Code 725.132, all facilities must be equipped with internal communications or clarm systems, a device to summon emergency assistance from local authorities, portable fire extinguishers, and fire spill control and decontamination equipment, and water at adequate volume and pressure unless none of the hazards posed by waste handled at the facility would require the specified equipment of this Section. You are in apparent violation of 35 III. Adm. Code 725.132 for the following reason(s): No decontemination equipment was available during the inspection.

Pursuant to 35 III. Adm. Code 725.133, all facility communications or alarm systems, fire protection equipment, spill control equipment and decentamination equipment, where required, must be tested and maintained as necessary to assure its proper operation in time of emergency. You are in apparent violation of this Section for the following reason(s): No evidence that fire protections and spill control equipment are being tested and maintained was observed during the inspection.



Pursuant to 35 III. Adm. Code 725.137, the owner or operator must eitempt to make arrangements to familiarize local police, fire departments, emergency response teams and hospitals as well as state authorities with the bazardous espects of the facility. These arrangements are to be included in the contingency plan. You are in apparent violation of 35 Ill. Adm. Code 725.137 for the following reason(s): He evidence that such arrangements had been attempted was evailable during the inspection.

Pursuant to 35 III. Adm. Code 725.151(a), each owner or operator must have a contingency plan. The contingency plan mest be designed to minimize hezards to homen health or the environment from fires, explosions or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil or surface water. You are in apparent violation of 35 III. Adm. Code 725.151(a) for the following reason(s): No contingency plan was available during the inspection.

Pursuant to 35 111. Adm. Code 725.153, a copy of the contingency plan and all revisions to the plan must be:

- Maintained at the facility: 2
- Submitted to all Iscal police departments, fire departments. hospitals and state and local emergency response teams.

You are in apparent violation of 35 III. Adm. Code 725.753 in that condition(s) a and b above was/were not complied with.

Pursuant to 35 111. Adm. Code 725.155, at all times there must be at least one emergency coordinator either on the facility premises or on call. You are in apparent violation of 35 III. Adm. Code 725,155 for the following reason: Ho emergency coordinator had been identified who would be at the facility or on call. · 中国 · 主要相似 · 一定被决定 · 在 · 生 · 如 · 一是的证

Pursuant to 35 III. Adm. Code 725.173, the owner or operator must keep a written operating record at the facility. The operating record must include the following:

- A description and the quantity of each hazardous waste received and the method(s) and date(s) of its treatment, storage or disposal at the facility as required by Appendix I of 35 Ill. Adm. Code 725.173;
- The location and quantity of each hazardous waste within the facility including cross-references to specific manifest document numbers:
- Records and results of waste analyses and trial tests;
- Summary reports and details of all incidents that require implementation of the contingency plan;



- Records and results of inspections:
- £. Monitoring, testing and other analytical data:
- **9.** All closure cost estimates and, for disposel facilities, all post-closure cost estimates.

You are in apparent violation of 35 Ill. Adm. Code 725.173 in that the operating record did not include item(s) a, b, c, d, e, f or g above.

Pursuant to 35 III. Adm. Code 725.175, the coner or operator must prepare and submit a single copy of an annual report to the director by March I of each year. You are in apparent violation of 25 111. Adm. Code 725.175 for the following reason(s): Annual reports for 1983, 1984 and 1985 were not available during the inspection.

Pursuant to 35 III. Adm. Code 725.212(a), by Pay 19, 1981, the owner or operator must have a written closure plan. A copy of the closure plan and all revisions must be kept at the facility until closure is completed and certified. The cleave plan must include at least:

- A description of how and when the facility will be partially closed, if applicable, and finally closed. The plan must identify how the requirements of Sections 725.211, 725.213, 725.214 and 725.215 and applicable requirements of 725.297, 725.328, 725.380, 725.410, 725.451, 725.461 and 725.504 will be set;
- h. An estimate of the meximum inventory of wastes in storage and in treatment at any time during the life of the facility:
- A description of the steps needed to decontaminate facility equipment and surrounding soft if necessary;
- An estimate of the expected year of closure and a schedule for final 0. closure:
- A provision for closure certification by an independent registered professional engineer.

You are in apparent violation of 35 III. Ado. Code 725.212(a) for the following reason(s): No closure plan was available during the inspection.

Pursuant to 35 III. Adm. Code 725.212(c), the cener or operator must submit his closure plan to the Director at least 180 days before the date he expects to begin closure. You are in apparent violation of 35 111. Adm. Code 725.212(c) for the following reason: You did not submit your closure plan as required.



Pursuant to 35 III. Adm. Code 725.242(d), the owner or operator must keep the following at the facility during the operating life of the facility: The latest closure cost estimate prepared in accordance with Sections 725.242(a) and (c) and, when this estimate has been adjusted in accordance with Section 725.242(b), the latest adjusted closure cost estimate. You are in apparent violation of 35 Ill. Adm. Code 725.242(d) for the following reason(s): Required closure cost estimates were not available during the inspection.

Pursuant to 35 Ill. Adm. Code 725.273(a), a container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. You are in apparent violation of 35 Ill. Adm. Code 725.273(a) for the following reason: Containers were observed stored open during the inspection.

Pursuant to 35 III. Adm. Code 725.274, the owner or operator must inspect areas where containers are stored at least weekly, locking for leaks and for deterioration caused by corrosion or other factors. You are in apparent violetion of 35 Ili. Adm. Code 725.274 for the following reason(s): No evidence that the required inspections are being conducted was observed during the inspection.

BF:mmc0782f/i4-19

# NON-NOTIFICATION AND NON-FILER DISPOSTION FORM

1.	Non-Notifier Non-Filer
2.	U.S.E.P.A. ID Number for Non-Filers ILDDD5070131
3.	Name of Facility: APOLLO METAL
	Facility Mailing Address: 11500 W. KING ST.
	FRANKLIN PARK TZ 66/3/ City or Town State Zip Code
4.	Location of Facility: 6657 S. OAK PARK AUE
	BEDFORD PARK IL 60638 City or Town State Zip Code
5.	Facility Contact: BILL SHAMASCO
	Name and Title  Phone Number: 3/2-458-4599 OR 3/2-767-6/6/  Area Code and Number
6.	Type of Hazardous Waste Activity if Determined:
	Generation Transportation
	Treat/Store/Dispose (Circle Applicable Activities)
	Underground Injection
7.	Description of State Follow-up Action (Including Name of State Assignee, File Data Reviewed, Person(s) Contacted by State, Date(s) and Type of Contact(s), and Information Obtained): GINO BRUNI IEPA/EPS
8.	List of Significant Apparent Violations: NON-NOTIFIER
	NON-FILER RECEIVED
9.	List of Supporting Documents Attached: ISS INSPECTION MAR 1 9 198
	[EPA-DLPC
	TO BE COMPLETED BY ENFORCEMENT SECTION
10.	Type of Enforcement Action Recommended: No enforcement action is recommended at the present their Bell backets die not achieve compliance upon agency ballowing, the backets will bereferred.
11.	Disposition Form Signed and Dated by State Enforcement Section:
	413186 Bare R. Jayelle

BB:14/10 1/31/

#### RCRA INSPECTION REPORT - INTERIM STATUS STANDARDS TREATME STORAGE, AND DISPOSAL FACILITIE Form A General Facility Standards

<u>General Ir</u>		6.0012	TEDA Miniba	-001100001
				r: <u>0316005151</u> Regulated As: <u>GEN/TSD</u>
		· ·		
	lity Name: APO			
	et: <u>6657 S.</u>			
				(E) Zip Code: <u>606.38</u>
	e: <u>312/458-459</u>		(G) County:	Cook
(H) Oper	ator: Apollo	Metal A		
	et: <u>66.57 S. C</u>			(1) 7: 0 : (6/77)
				(L) Zip Code: <u>60638</u>
	e: 312/458-459		(N) County:	Cook
	r: Apollo M			
	et: <u>11500 W.</u>	<del>-</del>		
	,			(S) Zip Code: <u>60131</u>
(T) Phon		•	(U) County:	Cook
D : (	312/767-61		718/ 1	(W) Time: (From) <u>/0:30</u> 改版 (To) <u>[:00</u>
Reg1001: <u>∧</u>	(v) bate of this	pection:/	<u> </u>	(H) Time: (Trom) 2000 (Tro)
Type of I	nspection.	(ISS) RECORD	REVIEW	SAMPLING CITIZEN COMPLAINT
I J PC OI I	Hapec Cron.			
1300 01 1	113500010111	CLOSED WITHDRA		OTHER PART B
1,500 01 1	napoc crom	CLOSED WITHDRA	AWAL	
		CLOSED WITHDR	AWAL	OTHER PART B
		CLOSED WITHDRA	AWAL	OTHER PART B
(X) Weath	er Conditions: <u>S</u>	CLOSED WITHDR	AWAL _/(Date	OTHER PART B
(X) Weath	er Conditions: <u>S</u> Section	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B
(X) Weath  Area  GTH	er Conditions: Section 725,113	CLOSED WITHDR	AWAL _/(Date	OTHER PART B e of Initial Inspection)
(X) Weath  Area  GTH  OTH	er Conditions: Section 725,113 725,115	CLOSED WITHDR	AWAL _/(Date	OTHER PART B e of Initial Inspection)
(X) Weath  Area  GTH  GTH	er Conditions: Section 725,113 725,115 725,116	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name
Area GTH OTH OTH	er Conditions: Section 725,113 725,115 725,116 725,117	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information
Area  GTH  OTH  OTH  OTH	section 725,113 725,115 725,116 725,117 725,132	CLOSED WITHDR	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Gino Bruni
Area  GTH  OTH  OTH  OTH  OTH	section 725,113 725,115 725,116 725,117 725,132 725,133	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Cino Bruni  Agency/Title
Area GTH GTH GTH OTH GTH GTH	section 725,113 725,115 725,116 725,117 725,132 725,133 725,137	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Gino Bruni
Area  GTH  GTH  GTH  GTH  GTH  GTH  GTH  GT	section 725,113 725,115 725,116 725,117 725,132 725,133 725,137 725,151 725,151	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Cino Bruni  Agency/Title  TEPA/EPS
Area  GTH  GTH  GTH  GTH  GTH  GTH  GTH  GT	section 725,113 725,115 725,116 725,117 725,132 725,133 725,137 725,133 725,133 725,133	CLOSED WITHDRA	AWAL _/(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Cino Bruni  Agency/Title  TEPA/EPS  Telephone
Area  GTH  GTH  GTH  GTH  GTH  GTH  GTH  GT	section 725,113 725,115 725,116 725,117 725,132 725,133 725,137 725,133 725,137 725,133 725,137	CLOSED WITHDRA	AWAL /(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Cino Bruni  Agency/Title  TEPA/EPS
Area  Area  GTH  GTH  GTH  OTH  GTH  GTH  GTH  GTH	section 725,113 725,115 725,115 725,116 725,137 725,137 725,137 725,133 725,137 725,133 725,137 725,137 725,137	CLOSED WITHDRA	AWAL /(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Cino Bruni  Agency/Title  TEPA/EPS  Telephone
Area  Area  GTH  GTH  GTH  OTH  GTH  GTH  GTH  GTH	er Conditions: Section 725,113 725,115 725,116 725,117 725,132 725,133 725,137 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133 725,133	CLOSED WITHDRA	AWAL /(Date	OTHER PART B e of Initial Inspection)  Preparer Information  Name  Gino Bruni  Agency/Title  TEPA/EPS  Telephone  312/345-9780  RECEIVED
Area  Area  GTH  GTH  GTH  OTH  GTH  GTH  GTH  GTH	section 725,113 725,115 725,115 725,116 725,137 725,137 725,137 725,133 725,137 725,133 725,137 725,137 725,137	CLOSED WITHDRA	AWAL /(Date	OTHER PART B  e of Initial Inspection)  Preparer Information  Name  Cino Bruni  Agency/Title  TEPA/EPS  Telephone  312/345-9780

IL 532-1343

(Y) Person(s) Interview SOHN WAIG		Telephone <u>312-458-4599</u> OR 767-6161
(Z) Inspection Particip <i>Gino Brun</i>		Telephone  312-345-9780
<u> </u>		
II. Section A: Scope of Ins	pection.	
E, and b.	standards for the treatment, storage or Ill. Adm. Code 725.101. Complete Inspect	
2. Place an "X" in disposal processority the applications.	n the box(es) corresponding to the facilitiesses, and generation and/or transportation cable sections and appendixes.	ty's treatment, storage or on activity (if any). Complete
r de la companya de	ess(es) (EPA Form 3510-3)	Inspection Form A section(s)
S01 V	storage in containers	. I
\$02	storage in tanks	J
	treatment in tanks	J
\$04	storage in surface impoundment	K, F
T02	treatment in surface impoundment	K, F
D83	disposal in surface impoundment	K, F
\$03	storage in waste pile	L L
D81	disposal by land application	M, F
D80	disposal in landfill	N, F
Т03	treatment by incineration	0, P
T04	treatment in devices other than tanks, impoundments, or incinerators	surface Q
Other <u>Activities</u>		
GENERATOR V	]	APPENDIX GN
TRANSPORTER	3	APPENDIX TR

- Indicate any hazardous waste processes, by process code, which have been omitted from Part A of the facility's permit application.
- 4. Indicate any hazardous waste processes (by process code and line number on EPA Form 3510-3 page 1 of 5) which appear to be eligible for exclusion per 35 III. Adm. Code 725.101(c). Provide a brief rationale for the possible exclusion.

IL 532-1343 LPC 194 (Rev. 6/85) Pg. 2 RECEIVED
MAR 1 9 1986
IEPA-DI.PC

Section B: GENERAL FACILITY	STANDARDS: (Pa	rt 725 Subpart B)	
	YES NO NI*	Remarks	÷
. Has the Regional Administrator been notified regarding:			
a. Receipt of hazardous waste from a foreign source?		FACILITY DOES NOT RECEIVE HAZ. WASTE. FROM A FOREIGN SOUNCE. NO FACILITY EXPANS	
b. Facility expansion?		STOPPED OPERATION IN OUT	·.
c. Change of owner or operator?		BUILDING HAY NOT BEEN S	OH.
2. General Waste Analysis:			
a. Has the owner or operator obtained a detailed chemical and physical analysis of the waste?			<del></del>
b. Does the owner or operator have a detailed waste analysis plan on file at the facility?			<del></del>
c. Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site?	<u> </u>	ODES NOT RECEIVE HAZ. W.	ME
<ol> <li>Security - Do security measures include (if applicable)</li> </ol>	:		
a. 24-Hour surveillance?			
or  b. i. Artificial or natural  barrier around facility?			
and ii. Controlled entry?			
<pre>c. Danger sign(s) at    entrance?</pre>	<u> </u>		
4. Owner or operator inspections:			
a. Does the owner or operator inspect the facility for malfunctions, deterioration, operator errors, and dischanges of hazardous waste that			-
may affect human health or the environment?		NO SUIDENCE OF SUCH THEFECTIONS.	<u></u>
*Not Inspected	D 1	RECEIVED	4

B-1

MAR 1 9 1986

IEDA DI DO

	and the Control of th
b. Does the owner or operator have an inspection schedule at the facility?	ES NO NI Remarks
<ul><li>c. If so, does the schedule address the inspection of the following items:</li><li>i. monitoring equipment?</li></ul>	NO INSPECTION
<pre>ii. safety and emergency equipment? iii. security devices?</pre>	SCHEOULE
<ul> <li>iv. operating and structural equipment (i.e. dikes, pumps, etc.)?</li> <li>v. type of problems to be looked for during the inspection (e.g. leaky fitting, defective pump, etc.)?</li> </ul>	
vi. inspection frequency (based upon the possible deterioration rate of the equipment)?	
<ul> <li>d. Are areas subject to spills inspected aily when in use?</li> <li>e. Does the owner or operator maintain an inspection log or summary of</li></ul>	NO EVIDENCE OF
f. Does the inspection log contain the following information:	NO INSPECTION LOG
<ul><li>i. the date and time of the inspector?</li><li>ii. the name of the inspector?</li><li>iii. a notation of the observations made?</li></ul>	

5. Do personnel training records include:

a. Job titles?

b. Job descriptions?

iv. the date and nature of any repairs or remedial actions?

c. Description of training?  d. Records of training?  e. Did facility personnel receive the required training by 5-19-81?  f. Do new personnel receive required training within six months?	
e. Did facility personnel receive the required training by 5-19-81?  f. Do new personnel receive required training within	TRAININ
f. Do new personnel receive required training within	
f. Do new personnel receive required training within	·
g. Do personnel training records indicate that personnel have taken part in an annual review of initital training?	
6. If required, are the following special requirements for ignitable, reactive, or incompatible wastes addressed?  TONITABLE & R ACTIVE WASTE	IE -
NO EVILENCE T	HAT
b. No smoking signs?  SPECIAL HANDLY  REQUEREMENT  PROTECTION FI	S AND
c. Separation and protection from ignition sources?  V  TCNITION SOU  ARE BEING	RCES
COMPLISHED	

RECEIVED

MAR 1 9 1986

IEPA-DLPC

4/82-A

Section C: PREPAREDNESS AND	PREVENTION: (1	Part 725 Subpart C)	W.
Maintenance and Operation of Facility:	YES NO NI	Remarks	
Is there any evidence of fire, explosion, or release of hazardous waste or hazardous waste constituent?			
If required, does the facility have the following equipment:			
a. Internal communications or alarm systems?	$ \frac{\checkmark}{}$	FACILITY STOPPE IN 1982	D OPER
b. Telephone or 2-way radios at the scene of operations?	<u> </u>		
c. Portable fire extinguishers, fire control, spill control equipment and decontamination equipment?		REQUIRE O DEC INHTION EQUI NOT AVAILAB	>M = MT
Indicate the volume of water and/or foar	π available for	fire control:	
CITY WATER.			
Testing and Maintenance of Emergency Equipment:			
a. Has the owner or operator established testing and maintenance procedures for emergency equipment?		NO EVIDENCE O	SF SUCH
b. Is emergency equipment maintained in operable condition?		NO EVEDÊNCE O	
<ul> <li>Has owner or operator provided immediate access to internal alarms? (if needed)</li> </ul>		FACILITY NERATING.	
5. Is there adequate aisle space for unobstructed movement?	<u>/</u>		
6. Has the owner or operator attempted to make arrangements with local authorities in case of an emergency	·		

YES NO NI Remarks

- Does the Contingency Plan contain the following information:
  - a. The actions facility personnel must take to comply with \$725.151 and 725.156 in response to fires, explosions, or any unplanned release of hazardous waste? (If the owner has a Spill Prevention, Control, and Countermeasures (SPCC) Plan, he needs only to amend that plan to incorporate hazardous waste management provisions that are sufficient to comply with the requirements of this Part (as applicable.)
    - b. Arrangements agreed by local police departments, fire departments hospitals, contractors, and State and local emergency response teams to coordinate emergency services pursuant to §725,137?
    - Names, addresses, and phone numbers (office and home) of all persons qualified to act as emergency coordinators?
    - d. A list of all emergency equipment at the facility which includes the location and physical description of each item on the list and a brief outline of its capabilities?
    - e. An evacuation plan for facility personnel where there is a possibility that evacuation could be necessary? (This plan must describe signal(s) to be used to begin evacuation, evacuation routes, and alternate evacuation routes?)
  - 2. Are copies of the Contingency Plan available at the site and local emergency organizations?

NO CONTINGENCY
PLAN AVAILABLE AT
SITE

\_ \_ \_

\_\_\_\_\_

\_\_\_\_\_\_\_

\_\_\_\_\_\_


RECEIVED

#### Emergency Coordinator

- a. Is the facility Emergency Coordinator identified?
- b. Is coordinator familiar with all aspects of site operation and emergency procedures?
- c. Does the Emergency Coordinator have the authority to carry out the Contingency Plan?

## 4. Emergency Procedures

If an emergency situation has occurred at this facility, has the Emergency Coordinator followed the emergency procedures listed in 725.156?



REQUIRING IMPLEMENTATION OF CONTINGENCY PLAN

# Section E: MANIFEST SYSTEM, RECORDKEEPING, AND REPORTING: (Part 725 Subpart E) Remarks Use of Manifest System a. Does the facility follow the procedures listed in §725,171 for processing each manifest? (Particularly sending a copy of the signed manifest back to the generator within 30 days after delivery.) b. Are records of past shipments retained for 3 years? Does the owner or operator meet requirements regarding manifest discrepancies? Not applicable to owners or operators of on-site facilities that do not receive any waste from off-site sources. 3. Operating Record Does the owner or operator maintain an operating record as required in 725.178? b. Does the operating record contain the following information: The method(s) and date(s)of each waste's treatment. storage, or disposal as required in 40 CFR Part 265

- Appendix I?-
- The location and quantity of each hazardous waste within the facility? (This information should be cross-referenced to specific manifest number, if waste was accompanied by by a manifest.)
- A map or diagram of each \*\*\*111 cell or disposal area

RECEIVED

MAR 1 U 1986

4/82-A

\*\*\* only applies to-disposal facilities

E-1 '

<sup>\*\*</sup> Not applicable to owners or operators of on-site facilities that do not receive any hazardous from off-site sources.

## Section G/H - CLOSURE/POST CLOSURE AND FINANCIAL (Part 725, Subpart's G+H)

		YES	NO	NI	Remarks
1.	Closure a. Is the facility closure				
	<ul><li>plan available for inspection?</li><li>b. Has the closure plan been submitted to the Director?</li></ul>	,	<u>√</u>		
*2.	Post Closure: Is the post closure plen available for inspection?		<u>v</u>		1.27
3.	Has the facility prepared a writ-			<u>.v_</u>	N / / 4
	ten estimate of the cost of closing the facility in accordance with the closure plan as specified in Section 725.212?		* ************************************	·	·
*4.	Has the facility prepared a written estimate of the annual cost of post-closure monitoring and maintenance of the facility?			V	NIA

MAR 1 9 1986 IEPA-DLPC

<sup>\*</sup> Applies only to disposal facilities.

# Section I - USE AND MANGEMENT OF CONTAINERS (Part 725, Subpart I)

		IEO NO NI	Nemar N3
۱.	Are containers in good condition? .	<u> </u>	
	Are containers compatible with waste in them?	<u> </u>	
3.	Are containers managed to prevent leaks?	$\Delta = 1$	
4.	Are containers stored closed?		CHRUME MATE ARE STO
5.	Are containers inspected weekly for leaks and defects.		HO EVENCE OF SUCH INSPECTIONS.
6.	Are ignitable and reactive wastes stored at least 15 meters (50 feet) from the facility property line? (Indicate if waste is ignitable or reactive).	<u> </u>	16N ARK STANCO.
7.	Are incompatible wastes stored in sepa- rate containers? (If not, the provisions of 35 Ill. Adm. Code 725.117(b) apply).		BUILDING.
8.	Are containers of incompatible waste separated or protected from each other by physical barriers or sufficient distance?	<u> </u>	

4/82-A

S	ec	t	i	on	A:	Scope
~		-	•	~		00000

1.	Complete this Appendix if the owner or operator of a TSD facility also general	् tes
	hazardous waste that is subsequently shipped off-site for treatment, storage,	`.
	or disposal.	

.'	•		YES	NO	NI	Remarks
1)		the operator have copies of the manifest ilable for review?				NO MANIFESTS
	were	fests for shipments in past months examined. The approx. number of manifests ments during that period were		<del>-</del> ∙		WERE AUAILABLE AT THE SITE
3)	foll cop fest	the manifest forms examined contain the lowing information: (If possible, make ies of, or record information from, manities) that do not contain the critical ments).	· <u>*</u>		- 18 To 18 T	•
	a.	Manifest document number?			Y	NO MANIFESTA
	b.	Name, mailing address, telephone number, and EPA ID number of Generator	-			
	c.	Name and EPA ID Number of Transporter(s)?	e		-	-
	d.	Name, address, and EPA ID Number Designated permitted facility and alternate facility?	************			
	e.	The description of the waste(s) (DOT shipping name, DOT hazard class, DOT identification number)?				
	f.	The total quantity of waste(s) and the type and number of containers loaded?		<del></del>		MAR 1 9 1986
	g.	Required certification?	**********	<del></del>		EPA-DLPC
	h.	Required signatures?				

- a. For manifests examined in (2) (except for shipments within the last 35 days), enter the number of manifests for which the generator has NOT received a signed copy from the designated facility within 35 days of the date of ship-
- For manifests indicated in (4a), enter the number for which the generator has submitted exception reports (35 III. Adm. Code 722.142) to the Regional Administrator.

Secti	on C	: PRE-TR	ANSPORT RF	TREMENTS	(Part 72	22, Subp	art C'		**************************************
						YES	NO -	NI	REMARKS
• , •	with (Reg	DOT regu uired pri	ged in acc lations? or to move te off-sit	ment of					NO WASTE READY FOR
	in a conc (Req	ccordance erning ha	e with DOT Izardous wa 'movement	ed and labe regulations ste materia of hazardou	ls?				MOVEMENT OFF SITE AT TIME OF INSPECTION
	tran	sporters	of hazardo						·
	gene	rates eit Adm. Cod	ther (A) ir de 722.134	its storage [See 725.10] If the inst Installation	ge facili )[(c)(7)] -allation	ty [725.]. Option elects	on B restr	icts all acc check this e_the follow	dous waste it cordance with 35 cumulation to box and skip wing observations:
		Is each with the date?	container of a	learly mark accumulation	ced	· · · ·			
	b.	Have mor since th	e than 90 o e date insp	days elapsed bected in (	d a)?			<u></u>	
F	с.	Do waste tanks fo	s remain in	n accumulat n 90 days?	ion				
	d.	or marke	container d clearly us Waste"?	and tank la with the wo	beled rds		· .		
Sect	ion I	D: - REC	ORDKEEPING	AND REPORT	ING (Par	rt 722,	Subpart D	)	
<u>-</u>	•					YES	NO	NI	REMARKS
1.	nee min	ded for h	azardous w tained for	and analyse aste deter- at least	S		<u></u>	<u> </u>	
Sect	ion	E: INTER	NATIONAL S	HIPMENTS (	Part 722	, Subpar	t E)	< <sup>21</sup> ,	
1.	Has exp	the inst orted Haz	allation i ardous Was	mported or te?	•			<u> </u>	
	(If as	answered applicabl	i Yes, comp e).	lete the fo	ollowing			·	
	a.	Exportin	ng Hazardou	ıs Waste; na	as a				

COORDINATOR 725 153 NO CONTINEOUS (LON JAME CONTINEOUS) - 424 2102 ASECORD 735 155 NO ENTOFEMENT NOTE FORMER BUYER JES SIS DO CHOUNTE PLAN CHESEL NATO DEVOLV DALLE OBLEGATED DOSK VARIATING. E.C.E.S.E. ALL DINUMA RESCOND CONTECTION AND REGIONAL MAY NOT CONDUCTED BY THE OPENION 703.131 BERRING A HUM FACILTY WITHOUT RORM YERMIT 732,140 THE FOLLOWING MAY VICENT: 703150 010 MI JUBRIT PART 665h-85h PARK FACILITY 767-6161 OR AT THE BEDFORD PARK FACILITY PACILITY MA SHAMASCO CAD BE REPORTED AT THE TOWNSHA THE WI STING SMOONGERY THE TO TUNDING THE JO SOME OF THE EQUIPMENT MR SHAMASCO IS IN CHARLE THE BUILDING FIXING PERKING PIPEL, AND REMOUNDS MR. USAI CANA INSTORMED ME THAT THEY ARE CLEANING THE FACILITY ASSOCIATION THE DAY A THE THE SHUWVECO OF TWO MAINTENANCE PEOPLE WILL BE THIS FROILITY BY THE PRESENT TIME MA WAIGHAD. TO STILL AND 28 CANTRINERS OF FLAMMABLE WASTEL OF DOBLINS OF CLERNER (CAUSTIC) 12 DRUMS OF CHROME 19 DRUMS OF DICKEL WASTE, 27 DRUMS OF CYMBIOL WASTE, 112 DOTA BER OF 1982, THEY ARE STERIMG ASPROXIENTED. COPPER BLATER. MPSTAL STOPPED CHERATION THE SEWER POLLO METAL IS BICKEL, CHROME, & APOLLO METAL WAS NOT DUMPING CYMNIOF WASTE INTO THINGSOFT STASITURE TO DESIGN OF THE The Total I year sand Tall study still study Conglains that Apple Metal was oungine Cyanios ON MARCH 7, 1986 THIS AGENCED AN ANONYMOUS

IEBV-DIBC

9861 6 T UVW

NARRATIVE

NARRATIVE SALES OF THE SALES OF
<u>NARRATIVE</u>
는 사용하는 100kg (100kg) 이 보는 사용 보는 사용 전 등 전 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
WERE MADE WITH LOURS AUTHORITIES 725. 133 NO FIRE PROTESTED
Spill CONTANT Equipment, & RECONTAMINATION EQUIPMENT WAY
AVAILABLE. 725.132 NO DECONTAMINATION EQUIPMENT
725117 NO SMOKING SIGHS WENT DESERVED DURING THE INSPECTION
NO EVIDENCE THAT PARCAUTION ARE BEING TAKEN TO PREVENT ACCIDENTAL
IGNITION OR REACTION OF IGNITABLE OF PREDITIVE WASTEN WERE
DRSERVED DURING THE INGESTICA- 725 116 PERSONNEL DIO
NOT RECEIUS ANNUAL REVIEWS OF INITIAL TRAINING
725.115 NO INSPECTION SCHEDULE 725.113 NO ANALYSIS
WERE CONDUCTED GRIOR TO STOPAGE.
-
RECEIVED
IEPA-DLPC
di N